# UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 7,019,971 B2

Page 1 of 1

APPLICATION NO.: 10/676977

DATED

: March 28, 2006

INVENTOR(S)

: Sabina Houle et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Figure 7

Reference number "24" between reference numbers "22" and "41" should read --70--Reference number "41" should read --71--

## Figure 8

Reference number "62" should read --65--

### Column 4

Line 18, "...edge seal apertures 23..." should read --...inlet apertures 23...-. Lines 18-19, "...substrate aperture 24, ..." should read --...vent aperture 24, ...-. Line 51, "...dissipation side 18..." should read --...dissipating side 18...--Lines 48-49, "...target side 68..." should read --...target surface 68...-.

#### Column 8

Line 36, "...expansion slot 62..." should read --...expansion slot 65...-. Lines 56-57, "...side portions 24..." should read --...side portion 70...--Line 58, "...top part 22..." should read --...top portion 22...-. Line 61, "...side portions 24..." should read --...side portion 70...--Lines 63-64, "...attachment material 41,..." should read --attachment material 71,...-Lines 66-67, "...heat dissipation appendages 39..." should read --...heat sink appendages 39...-.

#### Column 9

Line 58, "...dissipation side 18..." should read --...dissipating side 18...--.

Signed and Sealed this

Twelfth Day of June, 2007

JON W. DUDAS Director of the United States Patent and Trademark Office